Mock Inspection Report

4819 South 6th Street, Louisville, KY, USA

Mar 11, 2025

Performed by David Smith

This is a mock inspection report to demonstrate that the inspector has performed an inspection according to the InterNACHI® Standards of Practice.

Roof

View the InterNACHI® "Roof" inspection standard at https://www.nachi.org/sop.htm#roof.

Items Inspected

Roof-Covering Materials	No Defect(s) Observed
nspected from the ground with binocular.	



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Visit us online at **NACHI.ORG**



Gutters

No Defect(s) Observed

Downspouts

No Defect(s) Observed

Vents, Flashing, Skylights, Chimney, and Other Roof Penetrations

Minor Defect

Flashing is popped up and needs to be nailed down by a quilfied roofing contractor.



General Structure of the Roof (from the readily accessible panels, doors or stairs)

No Defect(s) Observed

System Descriptions

The Type of Roof-Covering Materials

• Asphalt Shingle

Reported Observations

Did you observe any indications of active roof leaks?

Exterior

View the InterNACHI® "Exterior" inspection standard at https://www.nachi.org/sop.htm#exterior.

Items Inspected

Exterior Wall-Covering Materials

Minor Defect

Aluminum siding



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Visit us online at NACHI.ORG





Eaves, Soffits and Fascia

No Defect(s) Observed

Windows (a representative number)

All Exterior Doors	No Defect(s) Observed
--------------------	-----------------------



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Visit us online at NACHI.ORG



Flashing and Trim

No Defect(s) Observed

Adjacent Walkways and Driveways

No Defect(s) Observed

Stairs, Steps, Stoops, Stairways and Ramps

No Defect(s) Observed

Porches, Patios, Decks, Balconies and Carports

No Defect(s) Observed

Railings, Guards and Handrails

Visit us online at NACHI.ORG

World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Vegetation, Surface Drainage, Retaining Walls and Grading of the Property (where they may adversely affect the structure due to moisture intrusion)

Cosmetic Defect

Recommend trimming tree back from house.



System Descriptions

The Type of Exterior Wall-Covering Materials

• Aluminum Siding

Reported Observations

Did you observe any improper spacing between intermediate balusters, spindles or rails?

Basement, Foundation, Crawlspace & Structure

View the InterNACHI® "Basement, Foundation, Crawlspace & Structure" inspection standard at https://www.nachi.org/sop.htm#basement.

Items Inspected

Foundation

Cosmetic Defect



Basement

Cosmetic Defect

Visit us online at **NACHLORG**

World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Crawlspace

No Defect(s) Observed



Structural Components

No Defect(s) Observed


System Descriptions

The Type of Foundation

Poured concrete and block.

The Location of the Access to the Under-Floor Space

• South side of house



Reported Observations



movement?

International Association of Certified Home Inspectors

World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Visit us online at **NACHI.ORG**

Did you observe indications of wood in contact with or near soil?	Not Observed
Did you observe indications of active water penetration?	Not Observed
Did you observe indications of possible foundation	Not Observed

Did you observe cutting, notching or boring of framing members?

Not Observed



Visit us online at NACHI.ORG

Heating

View the InterNACHI® "Heating" inspection standard at https://www.nachi.org/sop.htm#heating.

Items Inspected

Heating System (using normal operating controls)

No Defect(s) Observed



System Descriptions

Visit us online at NACHI.ORG

World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Location of the Thermostat for the Heating System	
• Living room	
The Energy Source	
• natural gas.	
The Heating Method	
• forced air gas furnace.	
Reported Observations	
Did you observe any heating system that did not operate?	Not Observed
Did you observe that the heating system was inaccessible?	Not Observed

Cooling

View the InterNACHI® "Cooling" inspection standard at https://www.nachi.org/sop.htm#cooling.

Items Inspected

Cooling System (using normal operating controls)

Not Inspected | Unsafe

System Descriptions

The Location of the Thermostat for the Cooling System

39 degree temp outside air temp.

Visit us online at NACHI.ORG

World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

The Cooling Method

• entral air conditioning system.



Reported Observations

Did you observe any cooling system that did not operate?



Visit us online at NACHI.ORG

World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Did you observe that the cooling system was inaccessible?

Plumbing

View the InterNACHI® "Plumbing" inspection standard at https://www.nachi.org/sop.htm#plumbing.

Items Inspected

Main Water Supply Shut-Off Valve

No Defect(s) Observed

Main Fuel Supply Shut-Off Valve

No Defect(s) Observed

Water Heating Equipment (including the energy source, venting connections, temperature/pressure-relief (TPR) valves, Watts 210 valves, and seismic bracing)

No Defect(s) Observed

Interior Water Supply (including all fixtures and faucets, by running the water)

No Defect(s) Observed

All Toilets (for proper operation by flushing)

All Sinks, Tubs and Showers (for functional drainage)

No Defect(s) Observed

Drain, Waste and Vent System

No Defect(s) Observed

Drainage Sump Pumps (with accessible floats)

Not Inspected | Not Present

System Descriptions

Whether the Water Supply is Public or Private (based upon observed evidence)

Public



Visit us online at NACHI.ORG

The Location of the Main Water Supply Shut-Off Valve

Basement




World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Visit us online at **NACHI.ORG**

The Location of the Main Fuel Supply Shut-Off Valve

South side of house.



The Location of Any Observed Fuel-Storage System

• N.A.

World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Visit us online at **NACHI.ORG**

The Capacity of the Water Heating Equipment (if labeled)

• 50 gal



Reported Observations

Did you observe deficiencies in the water supply?



Not Observed

Did you observe deficiencies in the installation of hot and cold water faucets?

Did you observe active plumbing water leaks?

Not Observed

Did you observe toilets that were damaged, had loose connections to the floor, were leaking, or had tank components that did not operate?


Electrical

View the InterNACHI® "Electrical" inspection standard at https://www.nachi.org/sop.htm#electrical.

Items Inspected

Service Drop

No Defect(s) Observed



Overhead Service Conductors and Attachment Point

Visit us online at NACHI.ORG

World Headquarters 1750 30th St Ste 301 Boulder, CO 80301


Service Head, Gooseneck and Drip Loops

No Defect(s) Observed

Service Mast, Service Conduit and Raceway

No Defect(s) Observed

Electric Meter and Base



Service-Entrance Conductors

No Defect(s) Observed

Main Service Disconnect

Visit us online at NACHI.ORG

World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Panelboards and Over-Current Protection Devices (circuit breakers and fuses)

Minor Defect

One or more conductors with the insulation stripped back to far. Recommend that its corrected by a licenced bonded electrical contractor.








World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Visit us online at NACHI.ORG



Service Grounding and Bonding

No Defect(s) Observed

Switches, Lighting Fixtures and Receptacles

No Defect(s) Observed

Ground-Fault Circuit Interrupter Receptacles and Circuit Breakers

Presence of Smoke and Carbon-Monoxide Detectors

No Defect(s) Observed

System Descriptions

The main service disconnect's amperage rating (if labeled)

• 100 Amp





The Type of Wiring Observed	
• Solid Copper	
Reported Observations	
Did you observe deficiencies in the integrity of the service-entrance conductors' insulation, drip loop, and vertical clearances from grade and roofs?	Not Observed
Did you observe any unused circuit-breaker panel opening that was not filled?	Not Observed
Did you observe the presence of solid conductor aluminum branch-circuit wiring, if readily visible?	Not Observed
Did you observe an issue with any tested receptacle?	Not Observed
Did you observe the absence of smoke and/or carbon monoxide detectors?	Not Observed



View the InterNACHI® "Fireplace" inspection standard at https://www.nachi.org/sop.htm#fireplace.

Items Inspected

Fireplaces and Chimneys (readily accessible and visible portions)	Not Inspected Not Present
Lintels Above the Fireplace Openings	Not Inspected Not Present
Damper Doors (by opening and closing them, if readily accessible and manually operable)	Not Inspected Not Present
Cleanout Doors and Frames	Not Inspected Not Present
System Descriptions	
The Type of Fireplace	
• N.A.	

Reported Observations



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Visit us online at NACHI.ORG

Did you observe evidence of joint separation, damage or
deterioration of the hearth, hearth extension or
chambers?

Not Observed

Did you observe manually operated dampers that did not open and close?

Not Observed

Did you observe the lack of a smoke detector in the same room as the fireplace?

Not Observed

Did you observe the lack of a carbon-monoxide detector in the same room as the fireplace?

Not Observed

Did you observe cleanouts not made of metal, pre-cast cement, or other non-combustible material?

Attic, Insulation & Ventilation

View the InterNACHI® "Attic, Insulation & Ventilation" inspection standard at https://www.nachi.org/sop.htm#attic.

Itams Inspected

Insulation in Unfinished Spaces (including attics, crawlspaces and foundation areas)	Not Inspected Inaccessible
Ventilation of Unfinished Spaces (including attic crawlspaces and foundation areas)	No Defect(s) Observed
Mechanical Exhaust Systems in the Kitchen, Bathrooms and Laundry Area	No Defect(s) Observed
System Descriptions	

The Type of Insulation Observed • no attic access.

The Approximate Average Depth of Insulation

N.A.

Reported Observations

Did you observe the general absence of insulation or ventilation in unfinished spaces?


Doors, Windows & Interior

View the InterNACHI® "Doors, Windows & Interior" inspection standard at https://www.nachi.org/sop.htm#doors.

Items Inspected

Doors and Windows (a representative number, by opening and closing them)

No Defect(s) Observed



Floors, Walls and Ceilings

Stairs, Steps, Landings, Stairways and Ramps

No Defect(s) Observed

Railings, Guards and Handrails

No Defect(s) Observed

Garage Vehicle Doors

Not Inspected | Not Present

System Descriptions

A Garage Vehicle Door (as manually-operated or installed with a garage door opener)

Installed with a garage door opener

Reported Observations

Did you observe improper spacing between intermediate balusters, spindles and rails for steps, stairways, guards or railings?



Did you observe photo-electric safety sensors that did not operate properly?

Not Observed

Did you observe any window that was obviously fogged or displayed other evidence of broken seals?